

### Hazardous Materials Inspection

Facility Owner		Facility I.D.			
Hope College		Transportation 176 East 19th Street Holland, MI 49423			
Site Contact		Asbestos Identified in Bldg.	□Yes ☑No		
Mr. Jerry Gunnink		Number of Floors	1		
178 East 11 <sup>th</sup> Street Holland, MI 49423		Basement	□Yes ☑No		
Telephone: 616-395-7999		Approximate Sq. Ft.	5,345		
Project No.	G080483A91				
Date of Inspection	September 17, 2008				
Name of Inspector	Mr. Christopher D. 0	Carew			
Inspector Accreditation No.	A35073				
Reference Documents	Table 1 – Description of Homogeneous Materials Table 2 – Bulk Sample Location Log Table 3 – Lead-Based Paint Results Appendix 1 – Floor Plans Showing Sample Sites Appendix 2 – Analytical Results				

## **Tables**

Table 1 - Description of Homogeneous Materials

Hazardous Materials Inspection Report

Inspection Date: September 17, 2008

Material Type MM MM SM MM Material Description 12" x 12" vinyl flooring and mastic 12" x 12" vinyl flooring and mastic 4" cove base and mastic (brown) Hope College, Transportation Center Yellow carpet mastic Drywall Number 3 4 2

Containing? Asbestos

Miscellaneous Material Notes: MM TSI SM HA

Thermal System Insulation Surfacing Material

Z z|z

z z Z

MM

Window caulk

9

Homogeneous Area

12/29/2008

Table 2 - Bulk Sample Location Log
Hazardous Materials Inspection Report
Inspection Date: September 17, 2008
Hope College, Transportation Center

Sample		Asbestos
Number	Sample Location	%
TRN-1-1	North bathroom, SE corner	None Detected
TRN-1-2	North bathroom, east wall, light switch	None Detected
TRN-1-3	South room, west wall	None Detected
TRN-2-1	North bathroom, SE corner	None Detected
TRN-3-1	North bathroom, south wall	None Detected
TRN-4-1	North bathroom, south wall	None Detected
TRN-5-1	South room, SW corner	None Detected
TRN-6-1	West warehouse, east wall, second window from south	None Detected

12/29/2008

#### **Table 3 - Summary of Paint Chip Sample Results**

Hazardous Materials Inspection Report Inspection Date: September 17, 2008 Hope College, Transportation Center

Sample ID	Sample Site	Description	Lead Concentration (% by wt)
TRN-PB-1	North bathroom, SE corner	White, interior	<0.01
TRN-PB-2	East warehouse, center door	Blue, interior	<0.01
TRN-PB-3	West warehouse, west wall, by door	Beige, interior/exterior	<0.02

# Appendix 1





engineers

scientists

architects

constructors

fishbeck, thompson, carr & huber, inc.

Hard copy is intended to be 11"x17" when plotted. Scale(s) indicated and graphic quality may not be accurate for any other size.

Hazardous Materials Inspections - 2008

Hope College Holland, Michigan

**SAMPLING LOCATIONS TRANSPORTATION CENTER** 176 E. 19TH STREET

PROJECT NO. G080483A91

FIGURE NO.

## Appendix 2



Phone: (317) 803-2997 Fax: (317) 803-3047 Email: indianapolislab@emsl.com

Attn: Dave Lutkenhoff Fishbeck, Thompson, Carr & Huber 1515 Arboretum Drive SE Grand Rapids, MI 49546

(616) 464-3992 Phone: (616) 575-3824

Project: G080483 Hope A91 TRN (Transportation)

Fax:

Customer ID: FTCH62
Customer PO: G080483 A91
Received: 09/22/08 10:15 AM
EMSL Order: 160814624

EMSL Proj:

Analysis Date: 10/6/2008 Report Date: 10/6/2008


### Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			<u>Asbestos</u>			
Sample	Location	Appearance	%	Fibrous	% Non-Fibrous	% Type
TRN 1 1 160814624-0001		White Non-Fibrous Homogeneous	20%	Cellulose	60% Gypsum 20% Non-fibrous (other)	None Detected
TRN 1 2 160814624-0002		White Non-Fibrous Homogeneous	20%	Cellulose	60% Gypsum 20% Non-fibrous (other)	None Detected
TRN 1 3 160814624-0003		White Non-Fibrous Homogeneous	20%	Cellulose	60% Gypsum 20% Non-fibrous (other)	None Detected
TRN 2 1 160814624-0004		Red/Brown Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
TRN 3 1 160814624-0005		Black Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
TRN 4 1 160814624-0006		White Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
TRN 5 1 160814624-0007		Yellow Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
TRN 6 1 160814624-0008		Red Non-Fibrous Homogeneous			100% Non-fibrous (other)	None Detected
Analyst(s)					All X. A.L.	
Melissa Wilson (8)					Richard Harding, Laboratory	Manager

Due to magnification limitations inherent in PLM, asbestos fibers in dimensions below the resolution capability of PLM may not be detected. The limit of detection as stated in the method is 1%. The above test report relates only to the items tested and may not be reproduced in any form without the express written approval of EMSL Analytical, Inc. EMSL's liability is limited to the cost of analysis. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government.

ACCREDITATION: NVLAP Lab Code 200188-0

or other approved signatory



Phone: (317) 803-2997 Fax: (317) 803-3047 Email: indianapolislab@emsl.com

Attn: Dave Lutkenhoff Fishbeck, Thompson, Carr & Huber 1515 Arboretum Drive SE Grand Rapids, MI 49546

Customer ID: FTCH62 Customer PO: G080483A91 Received:

09/22/08 10:15 AM

EMSL Order:

160813879

Fax: (616) 464-3992 Phone: (616) 575-3824

HOPE COLLEGE/G080483A91 TRN (TRANSPORTATION) Project:

EMSL Proj:

Report Date: 9/26/2008

#### Lead in Paint Chips by Flame AAS (SW 846 3050B and 7420\*)

Lab ID:	Analyzed	RDL	Lead Concentration	Notes	
0001	9/23/2008	0.01 % wt	<0.01 % wt		
Client Sc	imple TRN-PB-1			Collected:	9/18/2008
0002	9/23/2008	0.01 % wt	<0.01 % wt		
Client Sc	umple TRN-PB-2			Collected:	9/18/2008
0003	9/23/2008	0.02 % wt	<0.02 % wt		
Client Sc	umple TRN-PB-3			Collected:	9/18/2008

Doug Wiegand, Laboratory Manager or other approved signatory

Reporting limit is 0.01 % wt. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

\* slight modifications to methods applied Samples received in good condition unless otherwise noted. Quality Control Data associated with this sample set is within acceptable limits, unless otherwise noted

ACCREDITATIONS: AIHA ELLAP 157245

Date Printed: 9/26/2008 8:52:14 AM

PB w/RDL Page 1 of 1